

Inspection Photos
Location Name: Huck /41-28 Pad
Location #: 456482



Photo #1
Huck 41-28 (05-123-21882) Wellsite
Plugged & Abandoned | PA
Appears to be cut & capped
Unused Equipment
Unused flow line riser NOT marked & LO/TO



Photo #2
Huck 41-28 Battery
Shut-down | Inactive
Well: Plugged & Abandoned | PA
Unused Equipment