

Inspection Photos

ID: 150396

Operator: CHEMCO INC

Inspection Date: 10/7/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 1. Facing toward the tank battery. Sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 2. There is oil stained soil on the road surface near the tank battery. Approximately 4 ft. x 4 ft. area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 3. The berms around the tanks are worn down and not adequate to contain a spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 4. These pipe have oily waste at the ends with no containment. The tank on the right is not in use and is considered unused equipment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 5. There are propane tanks at the south side of the location which is a safety concern and are not properly stored.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 6. Pipe risers at the south side of the location have no LO/TO and are not protected from vehicle striking hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 7. Facing northeast at the south side of the location. Pipe risers at the south side of the location have no LO/TO and are not protected from vehicle striking hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 8. It appears material has been burnt onsite. Debris remains in this area with burnt remnants.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 9. There is various unused equipment such as pipe being stored at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 10. There is various unused equipment being stored at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150396 | Date: 10/7/2019

Inspection Photos



Photo 11. There is a barrel with unknown contents with no labeling.

