

Inspection Photos

API: 05-061-06093

Operator: CHEMCO INC

Inspection Date: 10/7/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06093 | Date: 10/7/2019

Inspection Photos



Photo 1. Facing northwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06093 | Date: 10/7/2019

Inspection Photos



Photo 2. The sign at the tank battery is not legible and is faded. There is no other sign posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06093 | Date: 10/7/2019