

Inspection Photos

API: 05-061-06088

Operator: CHEMCO INC

Inspection Date: 10/7/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-061-06088 | Date: 10/7/2019

Inspection Photos




Photo 1. Facing northwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06088 | Date: 10/7/2019

Inspection Photos



Photo 2. Well sign is posted.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06088 | Date: 10/7/2019

Inspection Photos



Photo 3. The cement pad is not in use and is considered unused equipment which needs to be removed. There are electrical wires and pipe risers shown by red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-061-06088 | Date: 10/7/2019