

Final Reclamation Inspection

October 7, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 305854

Inspection Document #: 697500693

Weld County, CO

SWNW Section 8 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RH FARMS #8-23
Location ID: 305854



Photo 1. Photo taken from the southern tank battery location, facing Northeast. Well location and tank battery will remain in-process, as the tank battery is not reflective of reference crops areas.

Inspection Photos
Location Name: RH FARMS #8-23
Location ID: 305854



Photo 2. Photo taken from the western tank battery location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: RH FARMS #8-23
Location ID: 305854



Photo 3. Photo taken western of the well location, facing Northeast. There is an active pipeline ROW being constructed near the PA well location.