

**Inspection Photos**  
**Operator: Kinder Morgan**  
**Location/API #: 083-06722**  
**Date: 10-3-2022**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. This area is straw mulched, mowed, and revegetating with young perennial grass seedlings and annual weeds such as Russian thistle observed.



Photo 3. View of the southern project area from the southwestern corner facing eastward, returned to dryland crop field.



Photo 4. View of the reference area dryland crop field, facing westward.