

Inspection Photos

Location Name: BASHOR STATE AA-66N63W /16SENE

Location #: 302517



Photo #1

Bashor State AA 16-17 (05-123-29262) Wellsite
Temporarily Abandoned | TA



Photo #2

Bashor State AA 16-01, 16-02, 16-07, 16-08, 16-17, 16-18
Battery Site

Abandoned: ALL equipment removed
Reclamation progressing