

Inspection Photos

API#077-05033

Operator: Caerus

Inspection Number: 692401419

Inspection Date: 9/19/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View North over Location Center.




Photo#2:
View South over Location Center.

September 19, 2019



Photo#3:
View East over Location Center.



Photo#4:
View West over Location Center.

September 19, 2019



Photo#5:
Bare areas that appear compacted.



Photo#6:
Bare areas that appear compacted.

September 19, 2019



Photo#7:
Weed infested area; insert - wattles remain on site.



September 19, 2019



Photo#8:
Bare areas; equipment position or turn around?

September 19, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Thomas API# 077-05033