

Inspection Photos
Location Name: Randall Creek 13-27H
Location ID: 424289



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Randall Creek 13-27H
Location ID: 424289



Photo 3 – Stained Soil at Wellhead



Photo 4 – NE Deadman Anchor not marked