

Inspection Photos

Location Name: BLADE RUNNER 23-21

API#: 05-071-07241

INSP. #: 695101507



Colorado Oil & Gas Conservation Commission
37.24059, -104.89481, 2322.0m, 264°
2019/10/09 15:48:24

PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: BLADE RUNNER 23-21

API#: 05-071-07241

INSP. #: 695101507



PHOTO 3: AREA OF IMPACTED GRAVEL/SOIL NEAR COMPRESSOR. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-9-19