

Inspection Photos
Location Name: Beisel #42-1
Location ID: 320427



Photo 1 WH Weeds on location



Photo 2 Stained soil around well head and on site

Inspection Photos
Location Name: Beisel #42-1
Location ID: 320427



Photo 3 Stained soil around Well head



Photo 4 unused equipment. Tubing laying on ground next to well head. Stained soil around well head.

Inspection Photos
Location Name: Beisel #42-1
Location ID: 320427



Colorado Oil and Gas Conservation Commission
Oct 9, 2019 11:36:43



Colorado Oil and Gas Conservation Commission
Oct 9, 2019 11:36:59

Photo 5 TNK BTRY Weeds in and around TNK BTRY

Photo 6 TNK BTRY Weeds in and around TNK BTRY

Inspection Photos
Location Name: Beisel #42-1
Location ID: 320427



Photo 7 Sep/ Meter house Weeds in and around equipment.

Photo 8 loc pic weeds on entire site.