

**Inspection Photos**  
**Location Name: BIG MEADOW 34-4**  
**API#: 05-071-07879**  
**INSP. #: 695101516**



**PHOTO 1: LOCATION**



**PHOTO 2: WELL SIGN**

Inspection Photos  
Location Name: BIG MEADOW 34-4  
API#: 05-071-07879  
INSP. #: 695101516




**PHOTO 3: SEVERAL AREAS OF IMPACTED SOIL AROUND ENGINE SKID. Properly treat or dispose of oily waste in accordance with 907.e. CA DATE 11-11-19.**



**PHOTO 4: TRASH, THE INSULATION ON SOUND WALL IS DETERIORATING AND PREADING ON LOCATION INSIDE SOUDWALL AND OUT. COMPLY WITH 603.f. CA DATE 10-18-19**



**Inspection Photos**  
**Location Name: BIG MEADOW 34-4**  
**API#: 05-071-07879**  
**INSP. #: 695101516**



**PHOTO 5: A NOTHER PHOTO SHOWING THE DETERIORATING  
INSOLATION.**