

Inspection Photos
Location Name: Huck /41-28 Pad
Location #: 456482



Photo #1

Huck 41-28 (05-123-21882) Wellsite

Plugged & Abandoned | PA

Appears to be cut & capped

Unused Equipment

*Unused flow line riser NOT marked & LO/TO
prior insp.*



Photo #2

Huck 41-28 Wellsite

Plugged & Abandoned | PA

Appears to be cut & capped

Unused Equipment

Unused flow line riser NOW marked & LO/TO

Inspection Photos
Location Name: Huck /41-28 Pad
Location #: 456482



Photo #3
Huck 41-28 Battery
Shut-down | Inactive
Well: Plugged & Abandoned | PA
Unused Equipment
prior insp.