

HALLIBURTON

iCem[®] Service

SRC ENERGY INC - EBUS

Golden Eagle 28C-1-M Production

Sincerely,
Meghan Jacobs

Legal Notice

Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

Table of Contents

1.0	Cementing Job Summary	4
1.1	Executive Summary	4
2.0	Real-Time Job Summary	7
2.1	Job Event Log	7
3.0	Attachments.....	9
3.1	Golden Eagle 28C-1-M Production – Job Chart	9

1.0 Cementing Job Summary

1.1 Executive Summary

Halliburton appreciates the opportunity to perform the cementing services on the **Golden Eagle 20C-1-M cement Production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Approximately 15 bbls of cement were returned to surface.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

Halliburton Fort Lupton

The Road to Excellence Starts with Safety

Sold To #: 359915		Ship To #: 3961577		Quote #:		Sales Order #: 0905753797				
Customer: SRC ENERGY INC-EBUS					Customer Rep: JOHN MEYERS					
Well Name: GOLDEN EAGLE			Well #: 28C-1-M			API/UWI #: 05-123-50130-00				
Field: WATTENBERG		City (SAP): EATON		County/Parish: WELD			State: COLORADO			
Legal Description: NE NE-6-6N-66W-1039FNL-498FEL										
Contractor: PRECISION DRLG					Rig/Platform Name/Num: PRECISION 562					
Job BOM: 7523 7523										
Well Type: HORIZONTAL OIL										
Sales Person: HALAMERICA/HB41307					Srvc Supervisor: Vitali Neverdasov					
Job										
Formation Name										
Formation Depth (MD)		Top			Bottom					
Form Type					BHST					
Job depth MD		15329ft			Job Depth TVD		7296			
Water Depth					Wk Ht Above Floor					
Perforation Depth (MD)		From			To					
Well Data										
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing		9.625	8.921	36	LTC	J-55	0	1823	0	1823
Casing	0	5.5	4.778	20	TXP-BTC	P110IC	0	15329	0	7296
Open Hole Section			8.5				1823	15349	1823	7296
Tools and Accessories										
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make	
Guide Shoe	5.5					Top Plug	5.5	1	N/A	
Float Shoe	5.5	1	.NA	15329		Bottom Plug	5.5	1	N/A	
Float Collar	5.5	1	N/A	15224		SSR plug set	5.5			
Insert Float	5.5					Plug Container	5.5	1	HES	
Stage Tool	5.5					Centralizers	5.5	232	N/A	
Fluid Data										
Stage/Plug #: 1										

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
1	Tuned Prime Cement Spacer	SBM FDP-C1337-18 CEMENT SPACER SYS	80	bbl	11.5	3.84		5		
2	ElastiCem	ELASTICEM (TM) SYSTEM	1241	sack	13.2	1.57		8	7.54	
3	NeoCem	NeoCem TM	840	sack	13.2	2.04		8	9.75	
4	MMCR Displacement	MMCR Displacement	20	bbl	8.34			8		
0.20 gal/bbl		MICRO MATRIX CEMENT RETARDER, 5 GAL PAIL (100003781)								
5	Water	Water	246.5	bbl	8.33			8		
1 gal/Mgal		CLA-WEB - BULK (101985043) / FE3								
6	MMCR Displacement	MMCR Displacement	70	bbl	8.34			8		
0.20 gal/bbl		MICRO MATRIX CEMENT RETARDER, 5 GAL PAIL (100003781)								
Cement Left In Pipe		Amount	0 ft		Reason			Shoe Joint		
Comment : 15 BBLs OF CEMENT BACK TO SURFACE. ESTIMATED TOP OF TAIL @ 7849'.										

2.0 Real-Time Job Summary

2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	Comb Pump Rate <i>(bbl/min)</i>	DH Density <i>(ppg)</i>	PS Pump Press <i>(psi)</i>	Comments
Event	1	Call Out	Call Out	6/9/2019	08:30:00	USER				ON LOCATION @ 15:30
Event	2	Depart Yard Safety Meeting	Depart Yard Safety Meeting	6/9/2019	13:35:00	USER				HELD JSA PRIOR LEAVING THE YARD
Event	3	Depart from Service Center or Other Site	Depart from Service Center or Other Site	6/9/2019	14:05:00	USER				
Event	4	Arrive at Location from Service Center	Arrive at Location from Service Center	6/9/2019	15:10:00	USER				44 MILES. DISCUSS NUMBERS AND PROCEDURE WITH CUSTOMER. RIG IS RUNNING CASING.
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	6/9/2019	15:27:00	USER				JSA PRIOR SPOTTING EQUIPMENT AND RIGGING UP
Event	6	Other	SPOT TRUCKS	6/9/2019	15:30:00	USER				SPOT TRUCKS
Event	7	Other	RIG UP	6/9/2019	15:40:00	USER				RIG UP ALL SURFACE LINES.
Event	8	Casing on Bottom	Casing on Bottom	6/9/2019	17:00:00	USER				CASING LANDED. RIG IS CIRCULATING THRU CRT
Event	9	Pre-Job Safety Meeting	Pre-Job Safety Meeting	6/9/2019	18:33:00	USER	0.00	8.62	1.00	DISCUSS HAZARDS AND JOB PROCEDURE WITH ALL PERSONAL INVOLVED
Event	10	Start Job	Start Job	6/9/2019	19:05:52	COM4	0.00	8.63	3.00	
Event	11	Check Weight	Check Weight	6/9/2019	19:11:41	COM4	0.00	8.67	7.00	
Event	12	Check Weight	Check Weight	6/9/2019	19:12:08	COM4	0.00	8.67	7.00	
Event	13	Pressure Test	Pressure Test	6/9/2019	19:16:00	USER	0.00	8.49	1852.00	LOAD LINE AND TEST TO 6470 PSI
Event	14	Drop Bottom Plug	Drop Bottom Plug	6/9/2019	19:18:00	USER	0.00	8.68	6445.00	DROP BOTTOM PLUG VERIFYIED BY CUSTOMER
Event	15	Pump Spacer	Pump Spacer	6/9/2019	19:20:00	USER	0.00	8.51	8.00	BATCH/ WEIGHT/ PUMP 80 BBLS OF TUNED SPACER @ 11.5 PPG WITH SURFACTANS.

Event	16	Pump Lead Cement	Pump Lead Cement	6/9/2019	19:35:00	USER	6.00	11.48	226.00	WEIGHT/ PUMP 1241 SKS (347 BBLS) OF ELASTICEM @ 13.2 PPG.
Event	17	Check Weight	Check Weight	6/9/2019	19:37:43	COM4	7.00	13.32	431.00	
Event	18	Pump Tail Cement	Pump Tail Cement	6/9/2019	20:22:00	USER	6.90	13.22	396.00	WEIGHT/ PUMP 840 SKS (305.2 BBLS) OF NEOCEM @ 13.2 PPG.
Event	19	Check Weight	Check Weight	6/9/2019	20:28:07	COM4	4.80	13.22	314.00	
Event	20	Shutdown	Shutdown	6/9/2019	21:13:00	USER	1.70	13.19	68.00	FINISHED PUMPING CEMENT
Event	21	Clean Lines	Clean Lines	6/9/2019	21:15:00	USER	0.00	13.22	18.00	WASH PUMPS AND LINES.
Event	22	Drop Top Plug	Drop Top Plug	6/9/2019	21:23:00	USER	3.90	8.08	119.00	DROP TOP PLUG VERYFYED BY CUSTOMER.
Event	23	Pump Displacement	Pump Displacement	6/9/2019	21:25:00	USER	0.00	8.07	3.00	336.5 BBLS OF FRESH WATER DISPLACEMENT. FIRST 20 BBLS WIRH MMCR, REMAINING WITH CLA-WEB AND BE3-S. LAST 70 BBLS WITH MMCR.
Event	24	Bump Plug	Bump Plug	6/9/2019	22:07:00	USER	2.70	8.13	2423.00	BUMP PLUG @ 2987 PSI 500 OVER FINAL LIFT PRESSURE.
Event	25	Other	SHIFT WET SHOE SUB	6/9/2019	22:12:00	USER	1.00	8.22	4282.00	PRESSURE UP 5110 PSI TO SHIFT WET SHOE SUB AND PUMP 6 BBLS WET SHOE.
Event	26	Shutdown	Shutdown	6/9/2019	22:14:00	USER	4.10	8.14	2614.00	
Event	27	Check Floats	Check Floats	6/9/2019	22:16:00	USER	0.00	8.12	2014.00	FLOATS HELD. 2.5 BBLS BACK.
Event	28	End Job	End Job	6/9/2019	22:17:41	COM4	0.00	8.05	5.00	
Event	29	Pre-Rig Down Safety Meeting	Pre-Rig Down Safety Meeting	6/9/2019	22:23:00	USER	0.00	8.06	5.00	HELD JSA PRIOR TO RIG DOWN

3.0 Attachments

3.1 Golden Eagle 28C-1-M Production – Job Chart

