

Inspection Photos

API#077-05028

Operator: Caerus

Inspection Number: 692401431

Inspection Date: 9/26/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
View over Location to Southeast.

September 26, 2019



Photo#2:
Sparsely vegetated area.



Photo#3:
Sparsely vegetated area.

September 26, 2019



Photo#5:
Sparsely vegetated area.

September 26, 2019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA HR Milholland API# 077-05028