

Inspection Photos

Location Name: Yellow Creek Federal

Location ID: 316373 & Spill/Release ID: 468668

Inspection Date: September 25, 2019



Photo #1 – Aerial view of the location. The black drop represents the spill location.



Photo #2 – View of the excavation with the 4-inch (produced water) and 6-inch flowlines (gas).



Inspection Photos

Location Name: Yellow Creek Federal

Location ID: 316373 & Spill/Release ID: 468668

Inspection Date: September 25, 2019



Photo #3 – View of the ditch on the west side of the road.



Photo #4 – View of the sediment catch located on the east side of the road.



Inspection Photos

Location Name: Yellow Creek Federal

Location ID: 316373 & Spill/Release ID: 468668

Inspection Date: September 25, 2019



Photo #5 - View of the sediment catch located on the east side of the road.



Photo #6 – View of the stockpiled soil located on the northwest side of the excavation.



Inspection Photos

Location Name: Yellow Creek Federal

Location ID: 316373 & Spill/Release ID: 468668

Inspection Date: September 25, 2019



Photo #7 – View of the flowline bedding that was excavated.



Photo #8 – View of the contaminated stock piled soil.

