

Inspection Photos
Location Name: Seeley Lake Pad
Location ID: 333330



Photo 1: Location



Photo 2: Wellhead Sign

Inspection Photos
Location Name: Seeley Lake Pad
Location ID: 333330



Photo 3: Wellhead



Photo 4: Tank Battery Sign

Inspection Photos
Location Name: Seeley Lake Pad
Location ID: 333330



Photo 5: Centralized Tank Battery



Photo 6: Debris (east of tank battery)

Inspection Photos
Location Name: Seeley Lake Pad
Location ID: 333330



Colorado Oil and Gas Conservation Commission
40.46814, -104.72752, 1410.8m, 46°
Oct 9, 2019 11:19:05

Photo 7: Weeds/ Debris (north of tank battery)