

Inspection Photos
Location Name: Miller 1
Location ID: 322653



Photo 1 – Oily material on top of concrete pad



Photo 2 – Improperly stored chemical containers.

Inspection Photos
Location Name: Miller 1
Location ID: 322653



Photo 3 – Improperly stored chemical containers and other trash.



Photo 4 – Concrete slabs, trash and weeds

Inspection Photos
Location Name: Miller 1
Location ID: 322653



Photo 5 – Weeds and trash.

Photo 6 – Location photo showing weed growth