

Inspection Photos

API: 05-017-07637

Operator: PELICAN HILL OIL & GAS

Inspection Date: 10/7/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-017-07637 | Date: 10/7/2019

Inspection Photos



Photo 1. Facing north at the center of the location. Winter wheat has been planted and is establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07637 | Date: 10/7/2019

Inspection Photos



Photo 2. Facing west at the center of the location. Winter wheat has been planted and is establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07637 | Date: 10/7/2019

Inspection Photos



Photo 3. Facing south at the center of the location. Winter wheat has been planted and is establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07637 | Date: 10/7/2019

Inspection Photos



Photo 4. Facing east at the center of the location. Winter wheat has been planted and is establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07637 | Date: 10/7/2019

Inspection Photos



Photo 5. View of winter wheat uniformly establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-017-07637 | Date: 10/7/2019