

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2019

Submitted Date:

10/15/2019

Document Number:

680305886**FIELD INSPECTION FORM**

Loc ID 337243 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 66190Name of Operator: OMIMEX PETROLEUM INCAddress: 7950 JOHN T WHITE ROADCity: FORT WORTH State: TX Zip: 76120**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**10 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	<a href="#">Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284361	WELL	PR	06/15/2007	GW	125-09956	BLEDSON 11-19-5-44	PR

**General Comment:**[Routine Site Inspection - SATISFACTORY](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Two track grassland		
Corrective Action		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:			Date: _____

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Other	# 0		
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

<b>Inspected Facilities</b>				
Facility ID: 284361	Type: WELL	API Number: 125-09956	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	GW			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's for erosion management](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine Site Inspection - SATISFACTORY</a>	schureky	10/15/2019