

Inspection Photos
Location Name: Hladky-O'Gorman #4
Location ID: 311331



Photo 1 WH sign has had new sticker installed



Photo 2 Alum pipe and conduit has been removed.

Inspection Photos
Location Name: Hladky-O'Gorman #4
Location ID: 311331



Photo 3 Flow line valves off well head are closed at time of inspection.