

MARALEX RESOURCES, INC.– 53255
API# 05-077-08018 FEDERAL #9-1-10-100
Inspection Date : 9/15/2019



Overview of location looking NE.



Wellhead with fence

MARALEX RESOURCES, INC.– 53255
API# 05-077-08018 FEDERAL #9-1-10-100
Inspection Date : 9/15/2019



Sign with 2" riser. Valve locked with hammer union bull plug.



Valve locked with hammer union bull plug.

MARALEX RESOURCES, INC.– 53255
API# 05-077-08018 FEDERAL #9-1-10-100
Inspection Date : 9/15/2019



Sign with 2" riser. Valve locked with hammer union bull plug.



Valve locked with hammer union bull plug.

MARALEX RESOURCES, INC.– 53255
API# 05-077-08018 FEDERAL #9-1-10-100
Inspection Date : 9/15/2019



Meter housing with 2" blind flange.



Meter housing with 2" riser.

MARALEX RESOURCES, INC.– 53255
API# 05-077-08018 FEDERAL #9-1-10-100
Inspection Date : 9/15/2019



Tank with 2" riser inlet. Outlet disconnected and plugged.



2" riser with bull plug..