

Construction and Stormwater Inspection

October 9, 2019

Operator: HIGHPOINT OPERATING CORPORATION- #10071

Location ID: 462024

Inspection Document #: 697500695

Weld County, CO

NWSW Section 5 T1N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Grinde /1-64-5_4 NWSW
Location ID: 462024



Photo 1. Photo taken from the northeastern perimeter of location, facing West. Photo illustrates a ditch BMP which is directed to a sediment trap along the northwestern perimeter of location.



Photo 2. Photo taken from the northwestern perimeter of location, facing South. Photo illustrates a sediment trap that was previously referenced.

Inspection Photos
Location Name: Grinde /1-64-5_4 NWSW
Location ID: 462024



Photo 3. Photo taken from the northeastern perimeter of location, facing West. Photo illustrates one of two topsoil stockpiles being stored along the northern perimeter of location.



Photo 4. Photo taken from the northwestern perimeter of location, facing East. Photo illustrates the second topsoil stockpile. Operator was still conducting topsoil salvage operations at the time of this inspection.