

## Inspection Photos

Location Name: ROTHE-65N63W /31SESW

Location #: 305178



**Photo #1**

**Rothe 24-31 (05-123-22602) Wellsite**

**Temporarily Abandoned | TA**

*Weeds  
prior insp.*



**Photo #2**

**Rothe 24-31 Wellsite**

**Temporarily Abandoned | TA**

*Weeds NOW appear mitigated*

**Inspection Photos**  
**Location Name: ROTHE-65N63W /31SESW**  
**Location #: 305178**



**Photo #3**  
**Rothe 24-31, 23-31 Battery**  
**Shut-down | Inactive**  
*Weeds*  
*prior insp.*



**Photo #4**  
**Rothe 24-31, 23-31 Battery**  
**Shut-down | Inactive**  
*Weeds NOW appear mitigated*

**Inspection Photos**  
**Location Name: ROTHE-65N63W /31SESW**  
**Location #: 305178**



Colorado Oil & Gas Conservation Commission  
40.34878, -104.47932, 1383.0m, 4°  
09/03/2019 02:54:03 PM



Colorado Oil & Gas Conservation Commission  
40.34879, -104.4793, 1383.0m, 356°  
10/16/2019 11:49:08 AM

**Photo #5**  
**Rothe 24-31, 23-31 Battery**  
**Shut-down | Inactive**  
*NFPA Label peeling, NOT legible  
prior insp.*

**Photo #6**  
**Rothe 24-31, 23-31 Battery**  
**Shut-down | Inactive**  
*NFPA label NOW legible*