

**Inspection Photos**  
**Location Name: Shannon Roberts #3**  
**Location ID: 321500**



Colorado Oil and Gas Conservation Commission  
Oct 16, 2019 10:37:20

**Photo 1 WH**



Colorado Oil and Gas Conservation Commission  
Oct 16, 2019 10:37:43

**Photo 2 loc pic Weeds on location**

**Inspection Photos**  
**Location Name: Shannon Roberts #3**  
**Location ID: 321500**



**Photo 3 sep/ meter run and produced water tank**



**Photo 4 dirt pile, Dead weeds, and trash**

**Inspection Photos**  
**Location Name: Shannon Roberts #3**  
**Location ID: 321500**



**Photo 5 Stained soil and mechanical issue on crude oil load out line**



**Photo 6 Weeds and trash on location.**