

Inspection Photos
Location Name: ROTHE-65N63W /31NESW
Location #: 305204



Photo #1
Rothe 23-31 (05-123-22642) Wellsite
Temporarily Abandoned | TA
Weeds
prior insp.



Photo #2
Rothe 23-31 Wellsite
Temporarily Abandoned | TA
Weeds NOW appear mitigated

Inspection Photos

Location Name: ROTHE-65N63W /31NESW

Location #: 305204



Photo #3

Rothe 23-31 (05-123-22642) Wellsite

Temporarily Abandoned | TA

*Access road: Weeds
prior insp.*



Photo #4

Rothe 23-31 Wellsite

Temporarily Abandoned | TA

Access road: Weeds ; NOW appear mitigated

Inspection Photos
Location Name: ROTHE-65N63W /31NESW
Location #: 305204



Photo #5
Rothe 24-31, 23-31 Battery
Shut-down | Inactive
Weeds
prior insp.



Photo #6
Rothe 24-31, 23-31 Battery
Shut-down | Inactive
Weeds NOW appear mitigated