

Final Reclamation Inspection

October 9, 2019

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 318986

Inspection Document #: 697500703

Weld County, CO

NENE Section 32 T2N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RUHL #1
Location ID: 318986



Photo 1. Google Earth aerial photo taken 2/29/2008 during active operations, prior to the new Crestone Peak Ruhl production facility. Photo illustrates the well location and well location access road.

Inspection Photos
Location Name: RUHL #1
Location ID: 318986



Photo 2. Google Earth aerial photo taken 5/31/2018, approximately 3 months prior to plugging operations. At the time of this inspection, the well location access road has not been reclaimed.

Inspection Photos
Location Name: RUHL #1
Location ID: 318986



Photo 3. Photo taken from the southern well location access road, facing West. Operator has failed to properly recontour and reclaim the well location road.

Inspection Photos
Location Name: RUHL #1
Location ID: 318986



Photo 4. Photo taken from the southern well location access road, facing North. Operator has failed to properly recontour and reclaim the well location road.

Inspection Photos
Location Name: RUHL #1
Location ID: 318986



Photo 5. Photo taken from the well location, facing West. Photo illustrates the well location has not been properly recontoured and gravel was observed throughout portions of the disturbance area.