

# Inspection Photos

API: 05-017-06433

Operator: MOUNTAIN PETROLEUM CORP

Inspection Date: 10/7/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-017-06433 | Date: 10/7/2019

## Inspection Photos



**Photo 1.** The access road to the location remains and appears to be a pre-existing road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 10/7/2019

## Inspection Photos



**Photo 2.** Facing west toward the location. The 2 cement pads, shed, and powerline were verified to be part of water infrastructure not associated with oil and gas operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 10/7/2019

## Inspection Photos



**Photo 3.** Facing northwest toward the location. The native vegetation at the location has re-established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 10/7/2019

## Inspection Photos



**Photo 4.** Facing southwest toward the location. The native vegetation at the location has re-established.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-017-06433 | Date: 10/7/2019