

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402162926

Receive Date:

10/02/2019

Report taken by:

KRIS NEIDEL

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Refer to Rules 340, 905, 906, 907, 908, 909, and 910

OPERATOR INFORMATION

Name of Operator: <u>KP KAUFFMAN COMPANY INC</u>	Operator No: <u>46290</u>	Phone Numbers
Address: <u>1675 BROADWAY, STE 2800</u>		Phone: <u>(303) 825-4822</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Max Knop</u>	Email: <u>mknop@kpk.com</u>	Mobile: <u>(720) 317-8161</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 11876 Initial Form 27 Document #: 401776946

PURPOSE INFORMATION

- | | |
|--|--|
| <input type="checkbox"/> 901.e. Sensitive Area Determination | <input type="checkbox"/> 909.c.(5), Rule 910.b.(4): Remediation of impacted ground water |
| <input type="checkbox"/> 909.c.(1), Rule 905: Pit or PW vessel closure | <input type="checkbox"/> Rule 909.e.(2)A.: Notice completion of remediation in accordance with Rule 909.b. |
| <input checked="" type="checkbox"/> 909.c.(2), Rule 906: Spill/Release Remediation | <input type="checkbox"/> Rule 909.e.(2)B.: Closure of remediation project |
| <input type="checkbox"/> 909.c.(3), Rule 907.e.: Land treatment of oily waste | <input type="checkbox"/> Rule 906.c.: Director request |
| <input type="checkbox"/> 909.c.(4), Rule 908.g.: Centralized E&P Waste Management Facility closure | <input type="checkbox"/> Other _____ |

SITE INFORMATION

N Multiple Facilities (in accordance with Rule 909.c.)

Facility Type: <u>SPILL OR RELEASE</u>	Facility ID: <u>441100</u>	API #: _____	County Name: <u>JACKSON</u>
Facility Name: <u>SPILL/RELEASE POINT</u>		Latitude: <u>40.781138</u>	Longitude: <u>-106.240976</u>
		** correct Lat/Long if needed: Latitude: _____	Longitude: _____
QtrQtr: <u>SWNW</u>	Sec: <u>2</u>	Twp: <u>9N</u>	Range: <u>79W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Rangeland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

SITE INVESTIGATION PLAN

TYPE OF WASTE:

☒ E&P Waste

☐ Other E&P Waste

☐ Non-E&P Waste

☒ Produced Water

☐ Workover Fluids

☐ Oil

☐ Tank Bottoms

☐ Condensate

☐ Pigging Waste

☐ Drilling Fluids

☐ Rig Wash

☐ Drill Cuttings

☐ Spent Filters

☐ Pit Bottoms

☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
Yes	SOILS	200' x 10'	Visual and soil analysis

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

During the previous operator, Bonanza Creek, and while conducting routine inspections, a release was observed along a flowline right of way. Approximately 7.4 bbl of oil and produced water were discharged to the ground surface. The well was shut-in immediately to stop the release. Incident response personnel were contacted to cleanup the discharged oil/water. The ground was frozen and the fluid was pooled on the ground surface.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

Soil samples were collected by previous operator on 10-12-2015 and 08-25-2016 with results showing levels above Table 910-1 standards. KPK collected samples on 09-26-2018 and will submit results as soon as they become available.

Proposed Groundwater Sampling

☐ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Proposed Surface Water Sampling

☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected 4

Number of soil samples exceeding 910-1 1

Was the areal and vertical extent of soil contamination delineated? Yes

Approximate areal extent (square feet) 2000

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 910-1

Surface Water

0 Number of surface water samples collected

 Number of surface water samples exceeding 910-1

If surface water is impacted, other agency notification may be required.

NA / ND

-- Highest concentration of TPH (mg/kg) 1000

NA Highest concentration of SAR

BTEX > 910-1 No

Vertical Extent > 910-1 (in feet) 0

 Highest concentration of Benzene (µg/l)

 Highest concentration of Toluene (µg/l)

 Highest concentration of Ethylbenzene (µg/l)

 Highest concentration of Xylene (µg/l)

 Highest concentration of Methane (mg/l)

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☒ Is further site investigation required?

Discrete soil sampling is required at historical composite sample locations to review progress from natural attenuation and define areas of impacted soil. Discrete soil samples will be collected at locations identified in the attached proposed sampling map. Samples will be collected from a depth of ~3 feet below ground surface. Field screening using ambient temperature head space measurements at 1-foot intervals of the sample location will be collected to help further define depth of impacted soil.

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No _____

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Impacted soil with analytical results exceeding Table 910-1 thresholds will be excavated and disposed of at the Walden Land Treatment Facility.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

Area showing exceedances of TPH based on the analytical results of the discrete soil samples will be excavated until total horizontal and vertical extent of the historical contamination is defined. Field screening results from ambient temperature head space measurements within the excavation area will be used to assist in defining extent of contaminations. Discrete soil samples will be collected from the base and walls of the final area of excavation. Soil samples will be analyzed for TPH - DRO, GRO & ORO, BTEX, pH, EC, and SAR.

Soil Remediation Summary

☒ In Situ

No Bioremediation (or enhanced bioremediation)

No Chemical oxidation

No Air sparge / Soil vapor extraction

Yes Natural Attenuation

Other _____

☒ Ex Situ

Yes Excavate and offsite disposal

If Yes: Estimated Volume (Cubic Yards) 50

Name of Licensed Disposal Facility or COGCC Facility ID # 427373

Excavate and onsite remediation

Land Treatment

Bioremediation (or enhanced bioremediation)

Chemical oxidation

Other _____

Groundwater Remediation Summary

No Bioremediation (or enhanced bioremediation)

No Chemical oxidation

No Air sparge / Soil vapor extraction

No Natural Attenuation

No Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Frequency: ☐ Quarterly ☐ Semi-Annually ☐ Annually ☒ Other KPK to provide update once soil analysis is received

Report Type: ☐ Groundwater Monitoring ☐ Land Treatment Progress Report ☐ O&M Report
☐ Other _____

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation? No

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards _____

E&P waste (solid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

Volume of E&P Waste (liquid) in barrels _____

E&P waste (liquid) description _____

COGCC Disposal Facility ID #, if applicable: _____

Non-COGCC Disposal Facility: _____

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

Do all soils meet Table 910-1 standards? _____

Does the previous reply indicate consideration of background concentrations? _____

Are the only residual soil impacts pH, SAR, or EC at depths greater than 3 feet below ground surface? _____

Does Groundwater meet Table 910-1 standards? _____

Is additional groundwater monitoring to be conducted? _____

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

Line was repaired and tested. Soil has been tilled periodically.

Is the described reclamation complete? No

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim? ☐ Final?

Did the Surface Owner approve the seed mix? Yes

If NO, does the seed mix comply with local soil conservation district recommendations? Yes

IMPLEMENTATION SCHEDULE

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 03/12/2015

Actual Spill or Release date, if known. 03/12/2015

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 03/12/2015

Date of commencement of Site Investigation. 03/12/2015

Date of completion of Site Investigation. 10/24/2019

REMEDIAL ACTION DATES

Date of commencement of Remediation. 03/12/2015

Date of completion of Remediation. _____

SITE RECLAMATION DATES

Date of commencement of Reclamation. _____

Date of completion of Reclamation. _____

OPERATOR COMMENT

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Max Knop

Title: Gen Mangr of Air Quality

Submit Date: 10/02/2019

Email: mknop@kpk.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: KRIS NEIDEL

Date: 10/16/2019

Remediation Project Number: 11876

COA Type**Description**

	Notice was provide via email of 10/17/2019 sampling event. It was also discussed that all samples in doc number 402197244 will be discrete.
	Provide notice to Environmental staff, Kris Neidel (kris.neidel@state.co.us) or 970-871-1963 72hrs prior to mobilization at beginning of all sampling events.
	All confirmation samples should be discrete samples, not composite samples as provided here (9/26/2018, 8/25/2016).

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

402162926	FORM 27-SUPPLEMENTAL-SUBMITTED
402162939	ANALYTICAL RESULTS
402162940	ANALYTICAL RESULTS
402162952	SOIL SAMPLE LOCATION MAP
402197244	SOIL SAMPLE LOCATION MAP

Total Attach: 5 Files

General Comments**User Group****Comment****Comment Date**

Environmental	The "increase" in DRO of sample SS04 (8/25/2016 at 487mg/kg to 9/26/2018 at 1000mg/kg), indicates that the area is not well defined. One additional discrete sample should be collected at the eastern extent of spill. The area of SS04 should have a total of 3 discrete samples.	09/05/2019
Environmental	COGCC does is not approving closure of any part of the spill path. All areas previously sampled should be sampled as a part of the 10/15/19 activities. See additional sampling comments.	09/05/2019

Total: 2 comment(s)