

Final Reclamation Inspection

October 9, 2019

Operator: PDC ENERGY INC - 69175

Location ID: 333292

Inspection Document #: 697500705

Weld County, CO

SWSE Section 24 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TOTEMS #34-24
Location ID: 333292



Photo 1. Photo taken from the well location, facing North. Photo illustrates the crop has already been harvested; therefore, COGCC staff could not perform a vegetative assessment. A follow up inspection will have to be conducted during crop growth.

Inspection Photos
Location Name: TOTEMS #34-24
Location ID: 333292



Photo 2. Photo taken from the associate tank battery location. Photo illustrates the tank battery is still in use for another nearby active well.