

# Final Reclamation Inspection

October 15, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

API: 05-123-11822

Inspection Document #: 697500711

Weld County, CO

SESE Section 11 T6N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 1.** Photo taken from the western compressor station, facing Southeast. Photo illustrates unmanaged weeds (Kochia and Russian thistle). Operator has failed to perform final reclamation activities.



Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 2.** Photo taken from inside the western compressor station, facing South. Photo illustrates the Operator has failed to perform final reclamation activities (i.e, gravel remains).



Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 3.** Photo taken from inside the southern compressor station, facing North. Photo illustrates the Operator has failed to perform final reclamation activities (i.e, concrete pad remains).  
Operator shall comply with the Environmental staff corrective actions regarding the oily material.

Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 4.** Photo taken from inside the southern compressor station, facing Northeast. See comments under Photo 3.



Inspection Photos  
Location Name: MILLER #1  
API: 05-123-11822



**Photo 5.** Photo taken from inside the eastern compressor station, facing East. See comments under Photo 3.