

**Inspection Photos**  
**Location Name: Crow Valley 7-62-30-2H**  
**Location ID: 428129**




**Photo 1 – Pumping Unit, stained soil at the south Well**



**Photo 2 – Tank Battery**

**Inspection Photos**  
**Location Name: Crow Valley 7-62-30-2H**  
**Location ID: 428129**



**Photo 3 – Stained soil at the Compressor**



**Photo 4 – Unused Chemical drum and containment on the South side of the South Pumping Unit**



**Inspection Photos**  
**Location Name: Crow Valley 7-62-30-2H**  
**Location ID: 428129**



**Photo 5 – Unused Chemical drum and containment on the North side of the South Pumping Unit**



**Photo 6 – Unused Chemical drum and containment on the North side of the North Pumping Unit**

**Inspection Photos**  
**Location Name: Crow Valley 7-62-30-2H**  
**Location ID: 428129**



**Photo 7 – Unused Chemical drum and containment on the South side of the Tank Berm**