

Inspection Photos
Location Name: Carl A Miller A #1
Location ID: 317739



Colorado Oil & Gas Conservation C



Colorado Oil & Gas Conservation C

Photo #1 Dead Weeds on lease access road

Photo #2 WH sign

Inspection Photos
Location Name: Carl A Miller A #1
Location ID: 317739



Photo #3 WH/PU Dead Weeds around lease ROW

Photo #4 Dead weeds behind electric panel and transformers.

Inspection Photos
Location Name: Carl A Miller A #2
Location ID: 317739



Colorado Oil & Gas Conservation Commission

Photo #5 Dead Weeds around lease ROW