

Inspection Photos
Location Name: Nessu #1
Location ID: 317790



Photo #1 WH sign has previous operator information

Photo #2 Weeds growing around location mostly dead



Inspection Photos
Location Name: Nessu #1
Location ID: 317790



Photo #3 Weeds growing on location mostly dead



Photo #4 Weeds growing on location mostly dead

Inspection Photos
Location Name: Nessu #1
Location ID: 317790



Photo #5 TB sign

Photo #6 TB

Inspection Photos
Location Name: Nessu #1
Location ID: 317790



Photo #7 no contents label/information



Photo #7 unused unmarked riser no LOTO