

Inspection Photos
Location Name: Meredith #2
Location ID: 333126



Photo #1 WH sign



Photo #2 PU

Inspection Photos
Location Name: Meredith #2
Location ID: 333126



Colorado Oil & Gas Conservation Commission



Colorado Oil & Gas Conservation Commission

Photo #3 TB sign

Photo #4 TB

Inspection Photos
Location Name: Meredith #2
Location ID: 333126



Photo #5 Heated Hor. Sep.

Photo #6 Weeds growing around Transformers and Electric panel

Inspection Photos
Location Name: Meredith #2
Location ID: 333126



Photo #7 Unused Meter box with exposed electric wire.

Photo #8 Stained soil under crude oil tank valve