

Inspection Photos
Location Name: State #11
Location ID: 336425



Photo #1 WH sign

Photo #2 PU

Inspection Photos
Location Name: State #11
Location ID: 336425



Photo #3 Stained soil around WH



Photo #4 broken belts at PU base

Inspection Photos
Location Name: State #11
Location ID: 336425



Photo #5 electric panel appears to be turned off



Photo #6 Kerr McGee well appears to be in process of PA