

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/09/2019

Submitted Date:

10/17/2019

Document Number:

689501006

FIELD INSPECTION FORM

Loc ID 319575 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10311

Name of Operator: SRC ENERGY INC

Address: 1675 BROADWAY SUITE 2600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
,		cogccinspections@srcenergy.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
111078	PIT				-	ADAMS 25-1	EI
243707	WELL	PR	08/16/2019	GW	123-11499	ADAMS 1-25	EI

General Comment:

COGCC Environmental Inspection to determine the status of pit facility ID 111078

Pit location was determined based on historic aerial imagery (circa 1999). COGCC personnel found no surface indication of a pit present in the location. However, the operator is instructed to submit a Form 27 for site characterization of the historic pit area.

Photos attached to document site condition at the time of inspection.

Inspected Facilities								
Facility ID:	111078	Type:	PIT	API Number: -	Status:	Insp. Status:	EI	
Facility ID:	243707	Type:	WELL	API Number: 123-11499	Status:	PR	Insp. Status:	EI

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Field inspections and pit inventory report documents a earthen pit was present on location. Pit location determined based on historic aerial imagery (circa 1999 - photo 5).

Corrective Action: Operator shall submit a Form 27 Site Investigation and Remediation Workplan for site characterization of the historic pit area.

Date: 10/09/2019

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment

User

Date

Contact area EPS Nikki Graber with any questions regarding Form 27 Submittal.

oakmank

10/17/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501007	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4966130