

Inspection Photos
Location Name: Binder 14-3
Location ID: 317859



Produced water vault placard on 9/19/19



Produced water vault placard on 10/17/19

Inspection Photos
Location Name: Binder 14-3
Location ID: 317859



Trash on 9/19/19



Trash on 10/17/19

Inspection Photos
Location Name: Binder 14-3
Location ID: 317859



Trash on 9/19/19



Trash on 10/17/19