

Inspection Photos

Location Name: Justine 1-10, Western 35-10, 28-15

Location ID: 327195



Production facility

Inspection Photos

Location Name: Justine 1-10, Western 35-10, 28-15

Location ID: 327195



Weeds on 9/25/19



Weeds on 10/17/19

Inspection Photos
Location Name: Justine 1-10, Western 35-10, 28-15
Location ID: 327195



Weeds and trash on 9/25/19



Weeds and trash on 10/17/19

Inspection Photos

Location Name: Justine 1-10, Western 35-10, 28-15

Location ID: 327195



Stored equipment on 9/25/19



Stored equipment on 10/17/19