

Inspection Photos
Location Name: SIEBRING /41-32
Location #: 332237



Photo #1

Siebring 41-32 (05-123-22021) Wellsite

Producing | PR

Emergency number NOT posted at wellsite



Photo #2

Siebring 41-32, 31-32, 32-32, 42-32, CNE-32 Battery

Active

Inspection Photos
Location Name: SIEBRING /41-32
Location #: 332237



Photo #3

Siebring 41-32, 31-32, 32-32, 42-32, CNE-32 Battery
Unused risers need marked



Photo #4

Siebring 41-32, 31-32, 32-32, 42-32, CNE-32 Battery
Unused risers need marked