

**Inspection Photos**  
**Location Name: Peffin 1-10H**  
**Location ID: 424875**




**Photo 1 – Pumping Unit**



**Photo 2 – Tank Battery**



**Inspection Photos**  
**Location Name: Peffin 1-10H**  
**Location ID: 424875**



**Photo 3 – Stained Soil at Wellhead**



**Photo 4 – Stained Soil at Engine Exhaust**



**Inspection Photos**  
**Location Name: Peffin 1-10H**  
**Location ID: 424875**



**Photo 5 – Stained Soil at Engine**

