

Inspection Photos
Location Name: JSR 4-1
Location ID: 313140



Photo 1. Overview of location taken facing north.

Inspection Photos
Location Name: JSR 4-1
Location ID: 313140



**Photo 2. No wellhead sign. Unmarked risers at wellhead.
Weeds on location.**



Photo 3. Meter run becoming debris.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: JSR 4-1
Location ID: 313140



Photo 4. Previous operator and emergency contact information only sign on location.



Photo 5. Electrical boxes set to "on".



Inspection Photos
Location Name: JSR 4-1
Location ID: 313140



Photo 6. Access road coming onto location.



Photo 7. Access road.

