

Final Reclamation Inspection

October 15, 2019

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 317511

Inspection Document #: 697500723

Weld County, CO

SESW Section 27 T8N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: KENNEDY #1
Location ID: 317511



Photo 1. Photo taken from the southern location, facing North. Operator has failed to perform final reclamation activities at the location (i.e., remove gravel, decompact, seedbed prep and seed).

Inspection Photos
Location Name: KENNEDY #1
Location ID: 317511



Photo 2. Photo taken from the southern location, facing West. See comments under Photo 1.