

Inspection Photos
Location Name: North Platte /43-13 Pad
Location #: 310743



Photo #1
North Platte 43-13 (05-123-26908) Wellsite
Weeds
prior insp.



Photo #2
North Platte 44-13 Wellsite
Weeds NOW appear mitigated
AMI – Operator provided photo

Inspection Photos
Location Name: North Platte /43-13 Pad
Location #: 310743



Photo #3

North Platte 44-13, 43-13, T-P-13HNB Battery

Active

. prior insp.