

Inspection Photos
Location Name: BASHOR PC AA /17-17
Location #: 419808



Photo #1

Bashor PC AA 17-17 (05-123-32357) Wellsite

Temporarily Abandoned | TA

Unused chemical tank

prior insp.



Photo #2

Bashor PC AA 17-17 Wellsite

Temporarily Abandoned | TA

Unused chemical tank – remains on site

prior insp.

Inspection Photos
Location Name: BASHOR PC AA /17-17
Location #: 419808



Photo #3

Bashor PC AA 17-17 (05-123-32357) Wellsite

Temporarily Abandoned | TA

Unused chemical tank – remains on site

This is 2nd Follow-up insp.



Photo #4

Bashor 17-11, 17-14

Bashor PC AA 17-17 – Battery Site

Abandoned – ALL equipment removed

**Muddy w/ puddles - Reclamation progressing
prior insp.**