

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 1 – Pumping Unit



Photo 2 – Tank Battery

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707




Photo 3 – Stained Soil at the front of Pumping Unit



Photo 4 – Stained Soil at the back of Pumping Unit

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707




Photo 5 – Stained Soil at Engine




Photo 6 – Stained Soil at Engine

Inspection Photos
Location Name: Planck 1-14H
Location ID: 424707



Photo 7 – Stained Soil at Exhaust



Photo 8 – Stained Soil at the back of Pumping Unit