

Inspection Photos

API#103-08672

Operator: Chevron

Inspection Number: 692401479

Inspection Date: 10/9/19



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to North.

October 9, 2019



Photo#2:

Large areas of senesced Kochia, at stage to break and tumble infest the site.

October 9, 2019

Photo#3:

Large areas of senesced Kochia, at stage to break and tumble infest the site.



Photo#4:
Large areas of senesced Kochia, at stage to break and tumble infest the site.

October 9, 2019

Photo#5:
Large areas of senesced Kochia, at stage to break and tumble infest the site.