

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582



Production facility



Wellhead

Inspection Photos
Location Name: Edward Hemple Unit #2
Location ID: 318582



Weeds on 8/15/19



Weeds on 10/18/19