

Inspection Photos
Location Name: McCallum Unit 19
Location ID: 324580



Photo 1. Overview of location taken facing northwest.



Inspection Photos
Location Name: McCallum Unit 19
Location ID: 324580



Photo 2. Stained soil at pump jack base.



Photo 3. Incomplete tank label; no contents, no capacity.

