

Inspection Photos
Operator: Swepi LP
Location/API #: 083-06413
Date: 10-11-2019



Photo 1. View of the project area from the northern edge facing center. Well pad is not reclaimed.



Photo 2. View of pits constructed and needing reclamation.



Photo 3. View of wood debris and salt cedar weeds within the eastern project area.




Photo 4. View of salt cedars (*Tamarisk* sp) within the eastern project area.



Photo 5. View of the southern fill slope from the southeastern edge facing westward.